

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002244**Date Inspected:** 05-May-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1500**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:****CWI Present:****Yes No****Inspected CWI report:** **Yes No N/A****Rod Oven in Use:** **Yes No N/A****Electrode to specification:** **Yes No N/A****Weld Procedures Followed:** **Yes No N/A****Qualified Welders:** **Yes No N/A****Verified Joint Fit-up:** **Yes No N/A****Approved Drawings:** **Yes No N/A****Approved WPS:** **Yes No N/A****Delayed / Cancelled:** **Yes No N/A****Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

The Quality Assurance (QA) Inspector, Mahlon Lindenmuth, arrived on site at the Zhenhua Port Machinery Company facility on Changxing island, China to periodically monitor welding and Quality Control functions. While on site the Quality Assurance Inspector observed and/or discovered the following.

QA Inspector, Lindenmuth, reviewed Material Test Reports (MTR) for plate material that will be used in the fabrication of OBG and Tower members. The review consists of verifying that the chemical and physical properties noted on the MTRs comply with contract documents. Not all MTRs are reviewed, MTRs that are reviewed are randomly selected from each "Batch" of MTRs that are submitted. The following is list of material Batches that have had MTRs randomly selected and reviewed:

Batch 132 Batch 143

Batch 129 Batch 141

Batch 150

Batch 131

Batch 153

They were no issues to note on the MTRs that have been reviewed. A TC-20 form has been filled out for each material Batch noted above. The TC-20 forms have been stored on the Team China Server under Materials.

Summary of Conversations:**Comments**

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Lindenmuth,Mahlon	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer
